


# 300620 EFFLUENT AN FOUNTAIN SUBMERSIBLE PUMP repair pieces

## PIECES:

| REF | #ITEMS   | DESCRIPTIONS      |
|-----|----------|-------------------|
| 1   | 350306   | Base screw (9)    |
| 2   | 350297   | Volute base       |
| 3   | 350528   | Impeller          |
| 4   | 350295   | Volute cover      |
| 5   | 350277   | Discharge reducer |
| 6   | 350278   | Mechanical seal   |
| 7   | 350125   | Oil seal          |
| 8   | 350340   | Lower bearing     |
| 9   | 450271   | Rotor             |
| 10  | 350340   | Upper bearing     |
| 11  | 350272   | Stator            |
| 12  | 450532   | Stator housing    |
| 13  | 350286.1 | Bearing housing   |
| 14  | 350118.1 | "O" ring          |
| 15  | 350273   | Capacitor         |
| 16  | 350288   | Upper casing      |
| 17  | 350289   | Screw             |
| 18  | 350294   | Power cable       |
| 19  | 450453   | Mechanical switch |



**Repair parts may be ordered from your authorized point of sale  
or from BUR-CAM PUMPS  
call us 514. 337.4415 or 1.800.361.1820**