


# PARTS BREAKDOWN




## PARTS LIST

#	DESCRIPTION
1	Shell (Welding Mask)
2	Auto Darkening Filter
3	Shade Control / Grind-Weld
4	Sensitivity Control/ Delay Time
5	Shade and Sensitivity Knobs
6	Front Cover Lens
7	Inside cover Lens
8	Sweatband (Cloth)
9	Headband Top Pad

10	Front Headband
11	Headband Back Pad
12	Headband Knob
13	Left Band & Right Band
14	Angle Adjusting Shim (left) & Angle Adjusting Shim (right)
15	Headband Fixing Screw x 2
16	Headband Rack (left) & Headband Rack (right)
17	Headband Knob x 2

# RÉPARTITION DES PIÈCES



## Liste des pièces

N°	DESCRIPTION
1	Coquille (casque de soudeur)
2	Filtre à assombrissement automatique
3	Contrôle de teinte/meulage-soudage
4	Commande de sensibilité/délai
5	Boutons de teinte et de sensibilité
6	Lentille de couvercle avant
7	Lentille intérieure du couvercle
8	Bandeau antisudation (tissu)
9	Empiècement supérieur du bandeau

10	Bandeau avant
11	Empiècement arrière du bandeau
12	Bouton du bandeau
13	Bande gauche et bande droite
14	Cale de réglage de l'angle (gauche) et cale de réglage de l'angle (droit)
15	Vis de fixation du bandeau x2
16	Support de bandeau (gauche) et support de bandeau (droit)
17	Bouton du bandeau x2