


TORIN INC. – VEHICLE LIFT IMPROVEMENTS

DATE: 20221114

PA SKU: 8964850

Torin Item: T9000-4ST

CURRENT	IMPROVEMENT
 There is a muffler at the air bleed hole on the cylinder	Torin improvement to the 4 post lift by adding a hose to prevent the cylinder from corrosion and debris getting into the hydraulic system
	 Add two connectors, one on the cylinder and one on the power unit
	 Remove the muffler at the air bleed hole, add a connector and a hose on the cylinder. The hose goes through the bridges and connects to the power unit
	 The hose goes from the cylinder and connects to the oil return hole on the power unit